

Volume3, Chapter 6 - BMP Maintenance

Users' Guidance:

If a UDFCD *Section* number in this Chapter is **skipped**:

It was adopted as is; please refer to that Section in the **corresponding UDFCD Manual**, Volume, Chapter and *Section*.

If a UDFCD *Section* number in this Chapter is **amended** or a new COFC *Section* in this **Chapter is added**:

It is **listed below**; please refer to it in **this document**.

If a UDFCD *Section* in this Chapter is **deleted** then it was **not** adopted by the City of Fort Collins;

The deleted UDFCD *Section* number will be **identified as deleted in the text below**.

(1) *Section 2.0* is adopted with the following modification:

All references to “UDFCD maintenance” are deleted.

(2) *Section 7.7* is amended to read as follows:

7.7 Sediment Removal from the Forebay, Trickle Channel and the BMP Bottom

Remove sediment from the forebay and trickle channel annually. If portions of the watershed are not developed or if roadway or landscaping projects are taking place in the watershed, the required frequency of sediment removal in the forebay may be as often as after each storm event. The forebay should be maintained in such a way that it does not provide a significant source of re-suspended sediment in the stormwater runoff. Ensure that the sediment is disposed of properly and not placed elsewhere in the basin.

Potential accumulation of sediment in the area directly upstream of the outlet structure at the bottom of the BMP must be checked for on a regular basis as well as after every significant storm event. Removal of accumulated sediment or debris must be done immediately when such sediment or debris blocks any portion of the outlet structure and must be done at least on a monthly basis between the months April and September as well as during any rainy period.