

### **Historic Preservation Services**

Community Development & Neighborhood Services 281 North College Avenue P.O. Box 580 Fort Collins, CO 80522.0580

970.416.4250 preservation@fcgov.com fcgov.com/historicpreservation

### CERTIFICATE OF APPROPRIATENESS – Minor Alteration ISSUED: April 16, 2020 (Addendum to March 16 Roof CoA) EXPIRATION: April 16, 2021

Mountain View Community Church of Fort Collins 201 Whedbee St. Fort Collins, CO 80524

Dear Property Owner:

This letter provides you with certification that proposed work to your designated Fort Collins landmark property has been approved without an application by the City's Historic Preservation Division (HPD) because the proposed work appears to be routine in nature with minimal effects to the historic resource, and meets the requirements of Chapter 14, <u>Article IV</u> of the Fort Collins Municipal Code.

The alterations reviewed include:

- 1. Partial in-kind roof replacement (sloped sections only) with asphalt shingle (previously approved on March 16, 2020).
  - Addendum Note: Work approved on March 16 modified by applicant to include replacement of decking, removal of asbestos tile roof shingles underneath asphalt shingles, and installation of new ridge and eave/edge vents.
- 2. Replacement of gutters and downspouts in-kind.
- 3. Repainting of trim features and windows to match gutters.
  - Condition Note 1: Painting should avoid overly abrasive physical or chemical removal of previous paint layers.
  - *Condition Note 2: Paint type should not be waterproof (i.e., should be breathable). Oil-based paints are generally encouraged for historic woodwork.*

Notice of the approved application has been provided to building and zoning staff to facilitate the processing of any permits that are needed for the work. Please consider the following National Park Service guidance as you complete this project:

- Preservation Brief #4, <u>*Roofing for Historic Buildings.</u>*</u>
- Preservation Brief #10, *Exterior Paint Problems on Historic Woodwork*

Please note that work beyond that indicated in your permit application/correspondence requires additional approval. Items requiring further approval include, but are not limited to, the following activities (items already approved indicated by strikethrough:

• Work affecting, or repair of, a chimney;

- Repair or replacement of historic decorative or functional features on or near the roof, such as fascia, purlins, brackets, eaves, gutters, and dormers;
- Replacement of substructure to the roof, such as sheathing/decking, rafters, or trusses;
- Installation of roof insulation above the sheathing that will result in more than a 2-inch increase in the roof height;
- Addition of new rooftop features including skylights, dormers, and new vents;
- Application of water sealants, including waterproof wood treatments or waterproof paints.

If the approved work is not completed prior to the expiration date noted above, you may apply for an extension by contacting staff at least 30 days prior to expiration. Extensions may be granted for up to 12 additional months, based on a satisfactory staff review of the extension request.

If you have any questions regarding this approval, or if I may be of any assistance, please do not hesitate to contact me. I may be reached at <u>jbertolini@fcgov.com</u> or 970-416-4250.

Sincerely,

Jim Bertolini Historic Preservation Planner



328 Remington Street, Fort Collins, CO 80524

# PITCH DIAGRAM

Pitch values are shown in inches per foot, and arrows indicate slope direction. The predominant pitch on this roof is 12/12



Note: This diagram contains labeled pitches for facet areas larger than 20.0 square feet. In some cases, pitch labels have been removed for readability. Blue shading indicates a pitch of 3/12 and greater. Gray shading indicates flat, 1/12 or 2/12 pitches. If present, a value of "F" indicates a flat facet (no pitch).

© 2008-2019 Eagle View Technologies, Inc. and Pictometry International Corp. – All Rights Reserved – Protected by European Patent Application No. 10162199.3 – Covered by one or more of U.S. Patent Nos. 8,078,436; 8,145,578; 8,170,840; 8,209,152; 8,515,125; 8,825,454; 9,135,737; 8,670,961; 9,514,568; 8,818,770; 8,542,880; 9,244,589; 9,329,749; 9,599,466. Other Patents Pending.

Report: 27726878



328 Remington Street, Fort Collins, CO 80524

## LENGTH DIAGRAM



Note: This diagram contains segment lengths (rounded to the nearest whole number) over 5.0 Feet. In some cases, segment labels have been removed for readability. Plus signs preface some numbers to avoid confusion when rotated (e.g. +6 and +9).

© 2008-2019 Eagle View Technologies, Inc. and Pictometry International Corp. – All Rights Reserved – Protected by European Patent Application No. 10162199.3 – Covered by one or more of U.S. Patent Nos. 8,078,436; 8,145,578; 8,170,840; 8,209,152; 8,515,125; 8,825,454; 9,135,737; 8,670,961; 9,514,568; 8,818,770; 8,542,880; 9,244,589; 9,329,749; 9,599,466. Other Patents Pending.

4/10/2019

**Premium Report** 



328 Remington Street, Fort Collins, CO 80524

### LENGTH DIAGRAM



Report: 27726878



Note: This diagram contains segment lengths (rounded to the nearest whole number) over 5.0 Feet. In some cases, segment labels have been removed for readability. Plus signs preface some numbers to avoid confusion when rotated (e.g. +6 and +9).

<sup>© 2008-2019</sup> Eagle View Technologies, Inc. and Pictometry International Corp. – All Rights Reserved – Protected by European Patent Application No. 10162199.3 – Covered by one or more of U.S. Patent Nos. 8,078,436; 8,145,578; 8,170,840; 8,209,152; 8,515,125; 8,825,454; 9,135,737; 8,670,961; 9,514,568; 8,818,770; 8,542,880; 9,244,589; 9,329,749; 9,599,466. Other Patents Pending.



# Your Multi-Purpose Exhaust Vent Solution.

### **EXHAUST INSTALLATION APPLICATIONS:**



LO459 1214

lomancovents

.

lomanco

MADE IN USA

Lomanco, Inc. • Iomanco.com • 1.800.643.5596







Want more info? Scan this OR code with your smartphone.

- MADE IN USA
- Lomanco, Inc. Iomanco.com 1.800.643.5596

Molded nail lines.



Texas Department of Insurance "Windstorm' Approved



Lomanco recommends balancing the intake ventilation system to the chosen exhaust ventilation system, a balanced system consists of 50% intake ventilation and 50% exhaust ventilation.

Lomanco ventilation calculations are based on the IRC/FHA standard of one square foot of ventilation for every 300 square feet of attic floor space. For ventilation calculators and additional information, visit our website, lomanco.com.

LO459 1214



#### Jim Bertolini

From: Sent: To: Subject: Attachments: Admin Assurance <admin@assurancecontractors.com> Thursday, April 16, 2020 4:18 PM Jim Bertolini Re: 328 Remington Street lo459 deckair da-4.pdf

Jim,

Please see the attached eave vent we are planning to install.

On Thu, Apr 16, 2020 at 3:50 PM Jim Bertolini <<u>ibertolini@fcgov.com</u>> wrote:

Sashelly,

Sorry to send multiple emails on this. Could you also clarify what type of eave vent you're planning to install? (a link to the product info online is fine). There's a couple different product types out there so I want to make sure. What I've often seen referred to as "edge vents" are excellent for a property like this where the eave line is a distinctive feature of the building. Something that's more of a soffit might be problematic due to the style and exterior materials of the building. Just send me a note once you're able. Thanks!

JIM BERTOLINI Pronouns: he/him/his

Historic Preservation Planner

Community Development & Neighborhood Services 281 North College Avenue 970-416-4250 office *jbertolini@fcgov.com* 

Tell us about our service, we want to know!

From: Jim Bertolini
Sent: Thursday, April 16, 2020 3:12 PM
To: Admin Assurance <admin@assurancecontractors.com
Subject: RE: 328 Remington Street</pre>

Sashelly,

Quick follow-up question on your fascia and window color question. I assume the church is interested in repainting those to match the gutters, is that correct? We typically advise against non-breathable paints like latex-based products in favor of oil-based as they are significantly healthier for the wood components. Thanks!

JIM BERTOLINI Pronouns: he/him/his

Historic Preservation Planner

Community Development & Neighborhood Services 281 North College Avenue 970-416-4250 office jbertolini@fcgov.com

Tell us about our service, we want to know!

From: Admin Assurance <<u>admin@assurancecontractors.com</u>> Sent: Wednesday, April 15, 2020 9:14 AM To: Historic Preservation <<u>preservation@fcgov.com</u>> Cc: Jim Bertolini <<u>jbertolini@fcgov.com</u>> Subject: 328 Remington Street

Good morning Jim,

Below you will find the details from work to be done on the Mountain View Church in regard to the re-roof:

1. The only work to be done is on the shingle portion, the flat roof areas are going to remain untouched. Shingles to be installed - OC Duration Storm in Driftwood

2. Asbestos company will remove 1 layer of slate, 1 layer of decking and 1 layer of shingles.

3. We will do a re-deck. Since we have to remove some layers of decking and slate, the height might stay around the same or less than an inch lower.

4. Ventilation: 76LF of ridge vent (all ridges) and 60LF of eave vents; we are doing 30' on the north side, 20' on the Eastside and 10' on the Westside. The will be installed 3 FT above the eave spread out evenly.

6. Gutters: current color is classic cream but we will be installing royal brown from Norandex - 147LF of gutters & 164Lf of downspouts to replace.

5. This job will take around two weeks of production

Attachments: gutter installation diagram, ventilation diagram, permit, and pictures.

**Notes**: In the permit work description it says that this project will be done by payroll employees and that is not the case. I have attached the permit application for reference.

On another note, what we would need to do if the church would like to change the windows and the fascia color? What would be the process?

Please feel free to contact me if you have any questions. Let me know if we are good to proceed with roof replacement if approve.

Thank you,

Sashelly Vargas

**Operations Coordinator** 

970-797-2502 ext 709

×

--

Note: Assurance Roofing is now Assurance Contractors!

Office number: 970.797.2502

FAX: 888.837.2137

admin@assurancecontractors.com

www.assurancecontractors.com

Facebook Page

Google Plus

---



#### Note: Assurance Roofing is now Assurance Contractors!

Office number: 970.797.2502 FAX: 888.837.2137 admin@assurancecontractors.com www.assurancecontractors.com Facebook Page Google Plus





















