

Historic Preservation Services

Community Development & Neighborhood Services 281 North College Avenue P.O. Box 580 Fort Collins. CO 80522.0580

970.416.4250 preservation@fcgov.com fcgov.com/historicpreservation

REPORT OF ALTERATIONS TO DESIGNATED RESOURCE

Site Number/Address: 527 Mathews St. Laurel School National Register Historic District ISSUED: August 22, 2022

Mark McCready c/o Matthew Lucas, Greater Front Range Roofing 527 Mathews St. Fort Collins, CO 80524

Dear Mr. Lucas:

This report is to inform you of the results of this office's review of proposed alterations to the Steudler Residence at 527 Mathews St., pursuant to Fort Collins Municipal Code, Chapter 14, Article IV. A copy of this report may be forwarded to the Colorado Office of Archaeology and Historic Preservation as well.

The alterations reviewed include:

• In-kind replacement of roof covering (asphalt)

Our staff review of the proposed work finds the alterations meet the SOI Standards for Rehabilitation and the project appears to be routine in nature with minimal effects to the historic resource, meeting the requirements of Article IV cited above.

Notice of the approved application has been provided to building and zoning staff to facilitate the processing of any permits that are needed for the work. Please note that work beyond that indicated in your permit application/correspondence requires additional approval. Items requiring further approval include, but are not limited to, the following activities:

- Work affecting, or repair of, a chimney;
- Repair or replacement of historic decorative or functional features on or near the roof, such as fascia, purlins, brackets, eaves, gutters, and dormers;
- Installation of roof insulation above the sheathing that will result in more than a 4-inch increase in the roof height; (note: uncovered portions at the eave should be covered with plain fascia or drip edge);
- Addition of new rooftop features including skylights, dormers, and large new vents (note: no further review is needed to install standard edge, ridge, or "turtle" vents required for meeting ventilation standards on new roofs).

If you have any questions regarding this report, or if I may be of any assistance, please do not hesitate to contact me. I can be reached at <u>yjones@fcgov.com</u> or at 970-224-6045.

Sincerely,

Yani Jones, Historic Preservation Planner