## City of Fort Collins Architectural Inventory Form Westside Neighborhood Survey Project

Page 1

Address:

416 N Grant Av

Site Number:

5LR9105

Parcel Number:

**Architectural Style:** 

Bungalow/Craftsman

Stories:

- 1

**Est Construction Date:** 

**Landmark Status:** 

Individually Eligible for NRHP:

Individually Eligible for Local Landmarking:

**V** 

Contributing to a District/Potential District:

V



**Primary Roof Form:** 

Hipped

Other:

Comment

Foundation:

Concrete

Other:

Comment

low, unpainted

**Exterior Wall Covering:** 

Lapped Board

Other:

Comment:

narrow



## CITY OF FORT COLLINS WESTSIDE NEIGHBORHOOD SURVEY

	416 H. GRAN	
Architectural Style: Bus	V (ACOU	No. of Stories:
Construction Date:	Sito #: 51 D	No. of Stories:
Constitution Date.	Site #: 5LR	Parcei #:
Primary Roof Form:	•	
□ Front Gabled □ Side Gabled	O Intersecting Gables / Hinned	☐ Hip w/ Gable(s) ☐ Flat ☐ Other
BLACIL	a merocoling dables 1 inpped	Trip w/ Gable(s) d Flat d Other
		lood/Shake Shingles ☐ Other
	Exposed Rafters	or Gable A-Wide Overhanging Eaves and/or Rake rlins or Beams 🛛 Boxed Eaves
,	,	
Exterior Walls and Wall Coveri	ng: 🎏 Wood Frame 🛭 Brick 🕻	☐ Stone ☐ Concrete Block  Shake Shingles ☐ Asbestos Shingles ☐ Stucco
SLapped Board Siding O Drop	Weatherboard Siding 🛭 Wood/S	hake Shingles   Asbestos Shingles   Stucco
		Stone 🛘 Other
Foundation: Concrete 🗆 Sa	ndstone 👊 Concrete Block 🗅 Ro	ockfaced Concrete Block   Other
LLOW, UNI	AINTED	25
Distinctive Features:		
☐ Imbricated Shingles Beneath 6	ables 🚨 Dormers: 🚨 Fron	t elev. 🗅 Side elev. 🗅 Gabled 🗅 Hipped 🗅 Shed
Porch Attributes: W/ MIPPO	ROOF, ON THE LR	SO BIZICK, ON
ਉÆront Porch ( ਉ∡Open or □ En	closed) with:   Gable   Shed	terior Chimney(s) □ Decorative Brickwork この Brzck なつ にといる。 XHip Roof; XClosed Rail □ Balustrade Railing
☐ Classical Columns or Pilasters	☐ Turned Spindle Post ☐ Mass	sive or Battered Piers X SQU ARSO PIEZ
Window Attributes:	·	~
Marrow 1-over-1 Double-Hung	Windows ☐ Sash and Transom	Window(s) w/ diamond light pattern transom(s)
		s Window(s) ☐ Casement Windows
☐ Dressed Stone Sills/Lintels 〔		The state of the s
		STYLE PORCH EXTENS NEARLY
THE FULL LECTA		os
Alterations: OLKZ GAB	LEO ADDITION	TO THE EAST (REAL)
ELENATION		
Condition: D Excellent M Goo	d D Fair D Poor Integr	rity: D. Evcellent D. Good D. Sair D. Boor
Condition: D Excellent  Goo	d draii drooi iiitegi	rity: Descellent Descond Fair Described 1955
Commence D Attached Comme	O Bata ah ad Canada Canada hutin	g? Y N Other 918 en Contributing? (Y
Garages: U Attached Garage	☐ Detached Garage Contributin	g? Y N Other 918 961 Contributing?
Annintan name i est cotet a la como	J. A	
Architectural Significance (Fiel		Ially Eligible for NRHP? ☐ Y 🕍
Indiv. Elig for Local Landmarki	ng? Sa □ N Contrb.	to Distr/Potential Distr? X Y □ N
Remarks:		
1		
/_/	,	
Date Recorded://8/01	Recorded By:	Carl McWilliams

## City of Fort Collins Architectural Inventory Form Westside Neighborhood Survey Project

Page 2

Address: 416 N Grant Av Distinctive Features: Bay Window(s): Canted Comment: Bay window Red brick interior Chimney **Exposed Rafters Roof Attributes:** Wide Overhanging Eaves and/or Rake Low Pitched Roof(s) Comp. Shingles Other: Comment Window Attributes: Narrow 1-over-1 Double Hung Other: Comment Front Porch Porches: Open porch Porch Attributes: Porch Closed Rail Porch Hip Roof Comment: **Squared Piers** Other Distinctive Features Very nice craftsman style porch extends nearly the full length of the façade **Alterations:** Older shed-roofed addition to the West(Rear) elevation; front porch is not historic Condition: Good Good Integrity: Garages: None Contributing? Yes 🗌 Other Outbuildings: Greenhouse Contributing? Yes 🔽 Corrugated Fiberglass Greenhouse type bldg Comments: Remarks: Date Recorded: 01/08/01

Carl McWilliams

Recorder: